



EXECUTIVE SUMMARY REPORT


01 DEC 2021 - 31 DEC 2021

CSA / CSA-TeamITR

INSTRUMENT SUMMARY

Instruments Monitored

- **Test Detector 1**
200150001-01
- **Test Detector 2**
200150001-02



- ✓ **Operational**
40% of time
- ? **Disconnected**
35% of time
- ! **Alarms**
24% of time
- ✗ **Out of Service**
0% of time


INSTRUMENT	INSTRUMENT STATUS	MIRION RESPONSE	UPTIME
Test Detector 1 Detector SN: LRH1234 Preamp SN: 020221 Cooler SN: 020221		TECH SUPPORT CASE OPEN	
Test Detector 2 Detector SN: LRH5678 Cooler SN: 020221		TECH SUPPORT CASE OPEN	

OPERATIONAL
 DISCONNECTED
 ALARM
 OUT OF SERVICE



TEAMITR | AUSTRALIA

CASE HISTORY OF COVERED INSTRUMENTS



[Additional Support Case Information](#)

ASSOCIATED TECHNICAL SUPPORT CASES

CASE NUMBER	INSTRUMENT	CASE SUBJECT	DATE OPENED	CASE STATUS
00038472	200150001-01-02	DeviceMetrics:PowerSupplyNeg12V-IPA-P8.020221 at 2021-12-17T13:59:16Z	17 Dec 2021	New
00038475	200150001-01	Detector Resolution	17 Dec 2021	New

ASSOCIATED WORK ORDERS

WORK ORDER	INSTRUMENT	TYPE	DESCRIPTION	SCHEDULED DATE	CLOSED DATE
WO-00041796	200150001-02	General On-Site Support		28 Dec 2021	